Hazardous Materials Technical Report Oregon Department of Transportation



Appendix B. Field Survey Photo Log



Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon PHOTOGRAPH LOG

Project No. 60537425



Photo No.Date:27/25/17Direction PhotoTaken:

n/a

Description:

View of unknown pipes extending up from ground along the east side of the building at Site 18. This building is proposed to be removed. Pipes could be related to the reported onsite underground storage tank (UST) at this site. This Site of Concern is within the Project Area and is ranked high priority.





3

Taken:

North

Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project

Site Location: Portland, Oregon

PHOTOGRAPH LOG

Project No. 60537425

Photo No. Date: 7/25/17 **Direction Photo Description:** View of NE Victoria Avenue along the east side of Site 18 to the left. This Site of Concern is within the Project Area and is ranked high priority. This building is proposed to be removed. View of NE Broadway and Site 84 in background.




Photo No. Date: 7/25/17 4 **Direction Photo** Taken:

North

Description:


View of I-5 to the west and downgradient of the building at Site 18 from NE Weidler Street. This Site of Concern is within the Project Area and is ranked high priority. This building is proposed to be removed.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon PHOTOGRAPH LOG


Project No. 60537425



Description:

View of UST fill ports in the western portion of the Site 23 from N Williams Avenue. Site 23 is within the Project Area and is ranked high priority.





West

Description:

View of N Weidler Street and N Wheeler Avenue intersection, showing Site 28, "Multicraft Vacant Lot" (250 N Broadway) and Site 29, "Heating Oil Tank" (240 N Broadway). These Sites of Concern are within the Project Area; Site 28 is ranked low priority and Site 29 is ranked high priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon

PHOTOGRAPH LOG

Project No. 60537425

Photo No.Date:77/25/17Direction PhotoTaken:

North

Description:

View of N Wheeler Avenue and N Broadway in background and Site 17, "Paramount Apartments" (253 N Broadway) beyond. This Site of Concern is within the Project Area and is ranked high priority.



Photo No.Date:87/25/17Direction PhotoTaken:

West

Description:

View of Site 14, "Williamsen & Bleid" (1835 N Flint Avenue and 270 N Hancock) along N Flint Avenue. View of unidentifiable 55-gallon drums at exterior property. This area is in the northern portion of the ODOT-proposed Hancock/Dixon cover. This Site of Concern is within the Project Area and is ranked medium priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon PHOTOGRAPH LOG

Project No. 60537425

Photo No.Date:97/25/17Direction PhotoTaken:

Northeast

Description:

View of Site 16, "PPS Fleet Garage Multnomah Co Fac & Prop Blanchard Bldg" (301 N Dixon Street). Former potential transformer location observed along exterior building (out of photo, to the left). This Site of Concern is within the Project Area and is ranked medium priority.



Photo No.	Date:
10	7/25/17
Direction Photo	
Taken:	

North

Description:

View of UST fill ports at the Site 16. This Site of Concern is within the Project Area and is ranked medium priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project

Site Location: Portland, Oregon

PHOTOGRAPH LOG

Project No. 60537425

Photo No.
11Date:
7/25/17Direction Photo
Taken:

West

Description:

View of Site 8, "Former Standard Brands Paint Co Store" (20 NE Hancock Street), now "Toyota Scion." This Site of Concern is within the Project Area and is ranked moderate priority.




Photo No.Date:127/25/17Direction PhotoTaken:

Southwest

Description:

View of the northern boundary of the Project Area along N Mississippi Avenue, beneath I-5 (Fremont Bridge). View of Site 149, "ODOT HWY Div Fremont Bridge Maint Fac/ OR ST HWY 1-2B Fremont Bridge" (845 N Graham Avenue). This Site of Concern is outside the Project Area and is ranked moderate priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon PHOTOGRAPH LOG

Project No. 60537425

Photo No.Date:137/25/17Direction PhotoTaken:

Southwest

Description:

View of Site 10, "Erickson Supply Co" (1905 N Williams Avenue), at the intersection of N Williams Avenue and N Hancock Street. This site was observed operating as Consolidated Supply Co. This Site of Concern is within the Project Area and is ranked moderate priority.




Photo No.Date:147/25/17Direction PhotoTaken:

Northeast

Description:

View of Site 42, a vacant/abandoned building at the corner of N Broadway and N Vancouver Avenue (1626 N Vancouver), adjacent to the west (left) of the ODOT-proposed Hancock/Dixon cover. This photo was taken within the Project Area and is ranked moderate priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon

PHOTOGRAPH LOG

Project No. 60537425

Photo No.Date:157/25/17Direction PhotoTaken:South

Description:

View of unidentifiable pipe protruding from pavement at the northwest corner of Site 28. View of NW Weidler Street in background and Rose Garden Arena parking garages beyond. This Site of Concern is within the Project Area and is ranked low priority.



Photo No.Date:167/25/17Direction PhotoTaken:

South

Description:

View of undeveloped land at the intersection of N Williams and N Broadway, within the proposed ODOT Hancock/Dixon cover. I-5 is located east (left) and downgradient. This photo was taken within the Project Area.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon PHOTOGRAPH LOG

Project No. 60537425

Photo No. Date: 7/25/17 17 **Direction Photo** Taken: West **Description:** View of exterior storage area of Site 91 along N Wheeler Avenue and N Wheeler Place. This Site of Concern is downgradient and within 1,000 feet of the Project Area, and is ranked low priority.



Photo No.Date:187/25/17Direction PhotoTaken:

South

Description:

View of undeveloped land adjacent to the west of Site 7, "Mammal Survey & Control Service" (216 N Tillamook Street). View of vagrant camp up the hill. View of I-5 downgradient. This Site of Concern is within the Project Area and is ranked low priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project

Site Location:

Portland, Oregon

PHOTOGRAPH LOG

Project No. 60537425

Photo No. Date: 7/25/17 19 **Direction Photo** Taken:

Southeast

Description:

View of Site 7 and adjacent property Site 6, "Multnomah Co SD 1 Student Trans Service" (2045 N Vancouver), observed operating as Seargent's Towing. Both Sites of Concern are within the Project Area and are ranked low priority.



Photo No. Date: 7/25/17 20 **Direction Photo** Taken:

Southeast

Description:

View of Site 6, observed operating as Seargent's Towing. This Site of Concern is within the Project Area and is ranked low priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon PHOTOGRAPH LOG

Project No. 60537425

Photo No.Date:217/25/17Direction PhotoTaken:

Southwest

Description:

View of Site 5, "Sherwin-Williams Co #9820" (510 N Russell Street), at the intersection of N Russell Street and N Commercial Avenue. View of I-5 in the background. This Site of Concern is within the Project Area and is ranked low priority.



Photo No.Date:227/25/17Direction PhotoTaken:

East

Description:

View of Site 47, beneath I-5. Fueling canopy is visible in the background to the right. This Site of Concern is located upgradient and within 1,000 feet of the Project Area and is ranked low priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon PHOTOGRAPH LOG

Project No. 60537425



Photo No.Date:247/25/17Direction PhotoTaken:

North

Description:

View of the exterior/backside of Site 84 at the intersection of NE Schuyler Street and NE 3rd Avenue. This Site of Concern is outside the Project Area and is ranked low priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon PHOTOGRAPH LOG

Project No. 60537425

Photo No.Date:257/25/17Direction PhotoTaken:

East

Description:

View of Site 85, "My Goods Market-76 #2705460" (425 NE Broadway). View of car wash on the northern portion of the property. This Site of Concern is outside the Project Area and is ranked low priority.



Photo No.Date:267/25/17Direction PhotoTaken:

North

Description:

View of Site 148, "Kadels Auto Body LLC Portland" (34 NE Grand Avenue), observed operating as ABRA Auto Body & Glass. This Site of Concern is outside the Project Area and is ranked low priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon PHOTOGRAPH LOG

Project No. 60537425

 Photo No.
 Date:

 27
 7/25/17

 Direction Photo
 Taken:

 Northwest
 Northwest

Description:

View of Site 144, "Block 76/67 Site" (15 NE Martin Luther King Blvd), observed under construction for a future potential apartment building. This Site of Concern is outside the Project Area and is ranked low priority.



Photo No.Date:287/25/17Direction PhotoTaken:

West

Description:


View of NE Couch Street and SE Grand Avenue intersection. View of Site 136, "Stark's Inc" (107 NE Grand Avenue), to the north (right) and Site 144 to the south (left). Both Sites of Concern are outside the Project Area and are ranked low priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project Site Location: Portland, Oregon PHOTOGRAPH LOG

Project No. 60537425



Description:

View of Site 143, "Powell, Vince O" (226 NE Grand Avenue), along NE Everett Street. This site was observed operating as Powell Motors. This Site of Concern is outside the Project Area and is ranked low priority.



Photo No.Date:307/25/17Direction PhotoTaken:

West

Description:

View of Site 139, "Gabriel Commercial Property" (203 NE Grand Avenue), at the intersection of NE Grand Avenue and NE Davis Street. This Site of Concern is outside the Project Area and is ranked low priority.





Hazardous Materials Technical Memorandum, I-5 Rose Quarter Improvement Project

Site Location: Portland, Oregon

PHOTOGRAPH LOG

Project No. 60537425

Photo No.Date:317/25/17Direction PhotoTaken:

West

Description:

View of unidentifiable materials storage at the intersection of N Graham Avenue and N Mississippi Avenue, adjacent to I-5 (Fremont Bridge in background). This photo was taken outside and downgradient of the Project Area.



Photo No.Date:327/25/17Direction PhotoTaken:

Northwest

Description:

View of a vagrant camp along N Mississippi Avenue beneath I-5 (Fremont Bridge). This photo was taken outside and upgradient of the Project Area.

